
























Conducted RF Spurious Emission


Condition	Mode	Frequency (MHz)	Max Value (dBc)	Limit (dBc)	Verdict
NVNT	1-DH5	2402	-38.8	<=-20	Pass
NVNT	1-DH5	2441	-39.47	<=-20	Pass
NVNT	1-DH5	2480	-37.21	<=-20	Pass
NVNT	2-DH5	2402	-39.14	<=-20	Pass
NVNT	2-DH5	2441	-37.63	<=-20	Pass
NVNT	2-DH5	2480	-36.57	<=-20	Pass
NVNT	3-DH5	2402	-39.24	<=-20	Pass
NVNT	3-DH5	2441	-37.98	<=-20	Pass
NVNT	3-DH5	2480	-34.46	<=-20	Pass

























APPENDIX 2-PHOTOS OF TEST SETUP

Note: See test photos in setup photo document for the actual connections between Product and support equipment.

*****END OF THE REPORT*****