Photo Report on

Test Setups
ION-E system
CAP-L7/80-58/17E/19 C-PE-F1
Cellular Repeater

This Photo Report contains the photos of the radiated tests in the 7layers test reports:
MDE_COMMSC_1701_FCCa
MDE_COMMSC_1701_FCCb
MDE_COMMSC_1701_FCCc
MDE_COMMSC_1701_FCCd

Test Report Reference: MDE_COMMSC_1701_FCC_Photo_Report

Test Laboratory:
7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany

Deutsche Akkreditierungsstelle
D-PL-12140-01-00

Note:
The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.



Photo 1: Test setup for radiated emissions measurements in semi-anechoic chamber (30 MHz to 1 GHz), rear side view

Photo 2: Test setup for radiated emissions measurements in semi-anechoic chamber (30 MHz to 1 GHz), front side view (with auxiliary equipment below table)

Photo 3: Test setup for radiated emissions measurements in fully-anechoic chamber (1 GHz to 10/20 GHz), rear side view, EUT vertical



Photo 4: Test setup for radiated emissions measurements in fully-anechoic chamber (1 GHz to 10/20 GHz), rear side view, EUT horizontal

Photo 5: Test setup for radiated emissions measurements in fully-anechoic chamber (1 GHz to 10/20 GHz), front side view (auxiliary equipment below table)