

Photo Report on

Test Setups

ION-M23 SDARS DC 1-Sector Passive

SDARS Remote Optical System

This Photo Report contains the photos of the radiated tests in the 7layers test reports:
MDE_COMSC_1901_FCCa

Test Report Reference: MDE_COMSC_1901_FCC_Photo_Report

Test Laboratory:

7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Deutsche
Akkreditierungsstelle
D-PL-12140-01-00

Note:

The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7layers GmbH

Borsigstraße 11
40880 Ratingen, Germany
T +49 (0) 2102 749 0
F +49 (0) 2102 749 350

Geschäftsführer/

Managing Directors:

Frank Spiller
Bernhard Retka
Alexandre Norré-Oudard

Registergericht/registered:

Düsseldorf HRB 75554
USt-Id.-Nr./VAT-No. DE203159652
Steuer-Nr./TAX-No. 147/5869/0385

*a Bureau Veritas
Group Company*

www.7layers.com




Photo 1: Test setup for radiated emissions measurements in semi-anechoic chamber (30 MHz to 1 GHz), rear side view



Photo 2: Test setup for radiated emissions measurements in semi-anechoic chamber (30 MHz to 1 GHz), detailed view, termination of RF connectors



Photo 3: Test setup for radiated emissions measurements in fully-anechoic chamber (1 GHz to 26 GHz), rear side view, EUT vertical



Photo 4: Test setup for radiated emissions measurements in fully-anechoic chamber (1 GHz to 26 GHz), right side view (termination of RF connectors)