

Photo Report on

Test Setups

ION-U System

EU L 25T/25T-Vac

Cellular Repeater

This Photo Report contains the photos of the radiated tests in the 7layers test report:
MDE_BVNBG_1802_FCCa

Test Report Reference: MDE_BVNBG_1802_FCC_Photo_Report

Test Laboratory:

7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Deutsche
Akkreditierungsstelle
D-PL-12140-01-00

Note:

The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7layers GmbH

Borsigstraße 11
40880 Ratingen, Germany
T +49 (0) 2102 749 0
F +49 (0) 2102 749 350

Geschäftsführer/

Managing Directors:

Frank Spiller
Bernhard Retka
Alexandre Norré-Oudard

Registergericht/registered:

Düsseldorf HRB 75554
USt-Id.-Nr./VAT-No. DE203159652
Steuer-Nr./TAX-No. 147/5869/0385

*a Bureau Veritas
Group Company*

www.7layers.com




Photo 1: Test setup for radiated emissions measurements in semi-anechoic chamber (30 MHz to 1 GHz), right side view with ancillary equipment on the table)




Photo 2: Test setup for radiated emissions measurements in semi-anechoic chamber (30 MHz to 1 GHz), front side view (with auxiliary equipment below table)




Photo 3: Test setup for radiated emissions measurements in fully-anechoic chamber with ancillary equipment on the table (1 GHz to 27 GHz), rear side view



Photo 4: Test setup for radiated emissions measurements in fully-anechoic chamber with ancillary equipment on the table (1 GHz to 27 GHz), left side view, detailed