


Annex 2 Test Setup Photographs

Photo No. 7, measurement in SAC, overall view 1:



Photo No. 8, measurement in SAC, overall view 2:



TR no.: 22087692-33486-1

2024-04-10

Photo No. 9, measurement in SAC, close view, EUT staying:




Photo No. 10, measurement in SAC, close view, EUT lying:



Photo No. 11, measurement in climatic chamber, overall view:





Photo No. 12, measurement in climatic chamber, close view:



End of Test Report
