


APPENDIX 3: Photographs of Test Setup

Radiated Spurious Emission

Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



Pre-check of Worst Case Position

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1




Photo 2

Antenna Terminal Conducted Tests



Photo 3




Photo 4

End of Report