

APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1



Photo 2

Radiated Spurious Emission

Below 1 GHz



Photo 1




Photo 2

Above 1 GHz




Photo 1



Photo 2

Pre-check of Worst Case Position

X-axis



Y-axis



Z-axis



Antenna Terminal Conducted Tests




Photo 1



Photo 2

End of Report