




APPENDIX 3: Photographs of test setup

Conducted Emission




Radiated Spurious Emission

below 1 GHz



above 1 GHz




Worst Case Position


X-axis



Y-axis



Z-axis



End of Report