

INTERNAL PHOTOGRAPHS

This document contains 8 photographs


Photograph No.1
ES700EPA Emergency Pendant removed from strap



Photograph No.2
ES700EPA Emergency Pendant removed from case



Photograph No.3
ES700EPA Emergency Pendant general internal view




Photograph No.4
ES700EPA Emergency Pendant internal view



Photograph No.5
ES700EPA Emergency Pendant internal view



Photograph No.7
ES700EPA antenna view



The antenna is printed, starts from point E1 on the left side and goes around the PCB

Photograph No.8
ES700EPA Emergency Pendant PCB second side view

