

Back view of the Panasonic BR167 DAG-SMR R5E car stereo unit. The unit is black and rectangular, mounted on a wooden surface. The central display screen shows a green circular error message: "FAILED CAMERA ERROR". Above the screen is a white label with the following information:

Panasonic
 Project: G-Designer
 Tel: +8643293759 976
BR167 DAG-SMR R5E
 Model Part No.: BR167 DAG-SMR R5E
 Component Part No.: A167 903 35 03
 OE Entry Date: 08.11.2018
 VIN: [Redacted]
 (VAG)
 Serial Number: PA1703B0000395

Mercedes-Benz
 DAG - Replacement
 C-Grade Price: 08
 Tel: +49 176 92942092
 Part No.: [Redacted]

QR Code: [Redacted]

Details	Version	VSB Part No.	Remarks
HW	18/45	A167 903 35 03	W/O CG
Hardware	18/45		
SW/APP	18/45 01		
SW/BOOT	18/45 01	A167 903 04 01	
CM/ATW	2018_29a		STAR_LAUG

External Over



External Under



External Right



External Left

